

Work Order ID 79117

Friday, February 03, 2012 1:00:55 PM

79117

Page 1

Item ID: DSI 9279-011

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Strobe Power Supply Relocation

Start Date: 1/20/2012 Start Qty: 3.00 ***3***

Cust Item ID:

Required Date: 1/23/2012 Req'd Qty: 3.00 ***3***

Customer: CU-DAR001

Reference: RMA RA111314 - RETURN

Approvals: Process Plan: *MLF*

Date: *12-02-03* Tooling:

Run Start ***NR1***

QC:

Date: SPC (Y/N):

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3246	Rev A1

100 QC5- Inspect part completeness to step on W/O 0.00

100

QC

Quality Control

Memo

INSPECT RA 111314 DSI 9279-011 B 75999 X 3

KITS ARE COMPLETE

NEEDS NEW PAPERWORK AND NEW BATCH NUMBER

110 Identify as per dwg & Stock Location: 0.00

110

Packaging

Packaging

Memo

0.00

CHG001

CHG001 (3)

Work Order ID 79117***79117***

Page 2

Friday, February 03, 2012 1:00:55 PM

Item ID: DSI 9279-011

Accept

N900040100Setup Start ***NS1***

Revision ID:

Item Name: Strobe Power Supply Relocation

Stop ***NS2***

Start Date: 1/20/2012 Start Qty: 3.00

3

Cust Item ID:

Required Date: 1/23/2012 Req'd Qty: 3.00

3

Customer: CU-DAR001

Reference: RMA RA111314

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
---------	--------	-----------	------------	------------	---------------	-------------

120

QC21- Final Inspection - Work Order Release

0.00


120

QC

Memo

0.00

Quality Control

M-L-5 12/02/06 ME
12-02-06

RA 111314 DSI 9279-011

B75999

Received @ Dart January 17th, 2011
Inspected@ Dart January 18th, 2011

Instructions for RA 111314 DSI 9279-011 B75999 CHG001

- Kits are complete
- Needs new paper work and **Labels**
- Needs to be restocked under a **NEW BATCH #**
- Needs new work order for restocking

Time Estimate = 1 HOUR ONLY (stores only)

Departments Required: Stores

Pictures Attached = N/A

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**